

Donington Park Event

5th – 6th September 2026

Report No: 4

To: The Stewards

Date: 05/09/2026

From: British GT Technical Team

Time: 18:59

Technical Report

Subject – Post qualifying report

The following checks were performed during and post qualifying.

<u>Parameter inspected</u>	<u>Car number</u>
Tyre allocation	All cars randomly checked throughout the session
Data*	All participating cars
Fuel samples	42, 44, 63, 74, 78, 84
Weight	42, 44, 63, 74, 78, 84
Ride height	42, 44, 63, 74**, 78, 84
Camber	42, 44, 63, 74, 78, 84
Front splitter protrusion	63, 74, 78, 84
Wing pylons	21, 27, 59
Front splitter	13, 18, 90
Restrictors seals	18
Turbo seal	21, 27, 59, 90
Ballast seals	13, 18, 21, 27, 59, 42, 44, 63, 74, 78, 84, 90

*Data reviewed by appointed data delegated person.

Comments

**Car 74 found to be under minimum rear ride height as per non-compliance report submitted to the stewards (DON/GT/26/1).

* Car 5, 42, 74 map found to not comply with current specified within BOP, data presented to the stewards by data delegate (DONGT5MG509, DONGT42MG509, DONGT74MG509)

No other issues to report



Stephen Rose
MotorSportUK Licence No. 170741



Matthew Godber
MotorSportUK Licence No 186444