

Donington Park Event

5th – 6th September 2026

Report No: 2 Version 2

To: The Stewards

Date: 05/09/2026

From: British GT Technical Team

Time: 11:40

Technical Report

Subject – Free practice report

The following checks were performed during and post pre-qualifying.

Parameter inspected

Car number

Tyre allocation

Random cars throughout the session

Data*

All participating cars

Driver/pit crew equipment

15, 61

Fuel samples

5, 15, 40, 44, 61

Driver exit test performed
(Both drivers)

7

*Data reviewed by appointed data delegated person.

Ballast was sealed post free practice and prior to pre-qualifying on all competing cars.

Comments

*Car 74 issue with data logging identified as per data delegate (Matthias Holle) email sent to Gethin Rees and supplied to the stewards (timed at 10:58).

Car numbers 5, 13, 27 failed to attend noise testing in line with the section 8 of the final instructions. All cars were noise tested by local scrutineers prior to track activity.

No other issues to report.



Stephen Rose
MotorSportUK Licence No. 170741



Matthew Godber
MotorSportUK Licence No 186444